National Transportation Safety Board NTSB ID: ANC97LA145B Aircraft Registration Number: N1123R FACTUAL REPORT Occurrence Date: 09/08/1997 Most Critical Injury: None AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place Local Time Time Zone State Zip Code 99727 1545 ADT **BUCKLAND** ΑK Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Model/Series Aircraft Manufacturer Type of Aircraft Cessna 208B Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

Same narrative as ANC-97-L-A145A

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ANC97LA145B

Occurrence Date: 09/08/1997

FACIDAL REPORT			Terice Date.	09/00/1991								
AVIATION		Occur	ccurrence Type: Accident									
Landing Facility/Approach Info	mation											
Airport Name		,	Airport ID:	Airport Eleva	tion	Run	way Used	Runway Length		h l	Runway	Width
BUCKLAND BY				24 Ft.	MSL	0						
Runway Surface Type:												
Runway Surface Condition:												
Type Instrument Approach: NONE												
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer			Model/							Number		
Cessna			208B						208B	0395		
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No N	umber of Seats:	10	Certifie	Certified Max Gross Wt.				8750 LBS Numbe			er of Engines: 1	
= - 11				Engine Manufacturer: Model/Serie P&W PT6A-114							Rated Power: 675 HP	
- Aircraft Inspection Information												
Type of Last Inspection			Date of Las	Date of Last Inspection Time Si			Since Last Inspection			Airframe Total Time		ime
AAIP			08/19/199	08/19/1997			69 Hours				3563	Hours
- Emergency Locator Transmitter (EL	T) Information											
ELT Installed? Yes	ELT Operat	ed? No		ELT Aided in Locating Accident Site?								
Owner/Operator Information												
Registered Aircraft Owner			Street Address P.O. BOX 1650									
BERING AIR INC.			City								Zip	Code
			NOME								997	762
Operator of Aircraft			Street Address Same as Reg'd Aircraft Owner									
Same as Reg'd Aircraft Owner			City							State	Zip	Code
-		Operator Designator Code: FXTA										
Operator Does Business As:						Op	erator Desig	nator Co	ode: FX	TA		
- Type of U.S. Certificate(s) Held:	Ai- O		No1	I Ain Taud								
Air Carrier Operating Certificate(s): C	ommuter Air C	arrier; C	n-demand	I AIF TAXI								
Operating Certificate:				Operator C	Certifica	ite:						
Regulation Flight Conducted Under: I	Part 135: Air Ta	xi & Co	mmuter									
Type of Flight Operation Conducted:	Unknown											
		FACTU	JAL REPO	RT - AVIATI	ON						F	Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: ANC97LA145B

Occurrence Date: 09/08/1997

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name			City			S	state	Date of Birth	Age			
On File	On File			0	n File	On File	38					
Sex: M Seat Occupied:	Prir	ncipal Profes	n Pilot	ot Certificate Number: On File								
Certificate(s): Airlin	e Transpor	t; Flight Inst										
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): Airplane Single-engine; Instrument Airplane												
Type Rating/Endorsement for	r Accident/In	cident Aircra	ft?			Current Bio	ennial Flig	ght Revi	ew?			
Medical Cert.: Class 1	Medica	l Cert. Status	S: Valid Me	dicalno wa	aivers/lim.		Date	of Last	Medical I	Exam: 03/17/19	997	
- Flight Time Matrix All A/C This Make and Model			Airplane Single Engine	Airplane Mult-Engine	Night	Ir Actual	Instrument ual Simulated		Rotorcraft	Glider	Lighter Than Air	
Total Time	Total Time 9875 1000		4800	5075	1100	90	900 100					
Pilot In Command(PIC)	9800											
Instructor 210					-						1	
Last 90 Days Last 30 Days	350 135											
Last 24 Hours	7											
Seatbelt Used? No	Shou	Ider Harness	Used? No		Toxic	ology Perf	ormed?	No	5	Second Pilot? No)	
	<u> </u>								I			
Flight Plan/Itinerary												
Type of Flight Plan Filed: Co	mpany VFF	₹										
Departure Point				•	State	A	Airport Identifier		Departure Time		Time Zone	
)		
Destination					State) A	irport Identifier					
NOORVIK	AK	1										
Type of Clearance: None												
Type of Airspace: Class 0	G											
Weather Information												
Source of Briefing:												
Method of Briefing:												
FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: ANC97LA145B

Occurrence Date: 09/08/1997

Occurrence Type: Accident

	FIYBOR			currence	- гуре.	Acciden	ıı						
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevation	n	WOF Distance From Accident Site					Direction From Accident Site		
	0000			0 Ft.	MSL			0 NM	0 Deg. M			g. Mag.	
Sky/Lowes	t Cloud Condition: Clear	•		0 Ft. AGL					Condition of Light: Day				
Lowest Ce	iling: None			0 Ft. AGL Visibility: 10			10	SM	Altiı	Altimeter: 29.00			
Temperature: 11 °C Dew Point:				1 °C	Wind	Direction: 90 Density Altitude:						:	Ft.
Wind Spee	ed: 12	Gusts:		Weather Condtions at Accident Site: Visual Conditions									
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensity	of Precipi	tation:	Unknown				
Restrictions to Visibility: None													
Type of Precipitation: None													
Accident	Information												
Aircraft Dar	mage:		Aire	craft Fire	t Fire: Aircraft I					losio	n		
Classificati	on:												
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pi	lot					1	1	1					
Second	d Pilot							1					
Studen	t Pilot							1					
Flight I	nstructor							1					
Check	Pilot							1					
Flight E	ngineer							1					
Cabin A	Attendants							1					
Other C	Crew							1					
Passen	gers					9	9	-					
- TOTAL A	ABOARD -					10	10	1					
Other G	Ground	0	C		0		(7					
- GRAND) TOTAL -	0	0		0	10		┥					
	'			•	•			•					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: ANC97LA145B

Occurrence Date: 09/08/1997

Occurrence Type: Accident

	rativ			

Investigator-In-Charge (IIC)

SCOTT R. ERICKSON

Additional Persons Participating in This Accident/Incident Investigation:

GREG HIBDON FAA-AL-FAI-FSDO FAIRBANKS, AK